Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/90009MD1109/1

Work Order Type: Weatherization

Audit Name: Audit-90009MD1109

CLIENT INFORMATION

Client Name: 90009MD1109 Address:

37138 Client ID: 90009MD1109

Alt. Client ID: Davidson

CLIENT CONTACT INFORMATION

90009MD1109 Applicant/Person of **V**

Record

AGENCY INFORMATION

Agency: Metropolitan Development and Housing Agency Agency Phone: (615) 252-8546

Address: 701 S 6th Street Fax:

> Nashville, TN 37206 Email Address:

Agency Contact: Radford, Randy Work Phone: (615) 686-3245

Cell Phone: (615) 335-7428

Email Address: Randy@energyhoundz.com

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Contractor to follow 2006 International Residential Code as adopted by the City of Nashville or Davidson County as applicable.

Client Name: 90009MD1109 Client ID: 90009MD1109 Alt. Client ID: Davidson

Work Order (Bid Form)

Work Order Name: WO/90009MD1109/1 Report Run On: 5/24/2010

DOE Weatherization Assistant

Version 8.6.0 Page 1 of 8

Measures

Comment	3 Windows		Componen	ts		I	nspected
			Estimated	1		Actual	
# Material / Labor Description	on / Comment Un	its Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor		1					
2 Windows		1					
		•					
Other Detail							
] [
		Measu	re Sub Total:			Sub Total:	
Measure 2 Replace Brok WD8 (Approx. Comment Responsibility of o window glass.	. 11.75 x 28)		Componen		orderin		nspected
milden glade.						9	
			Estimated	ı		e Actual	
# Material / Labor Description	on / Comment Un	its Qty	Estimated Unit Cost	l Total	Qty	-	Total
# Material / Labor Description 1 Labor	on / Comment Un	its Qty			Qty	Actual	Total
•	on / Comment Un	•			Qty	Actual	Total
1 Labor 2 Windows	on / Comment Un	1			Qty	Actual	Total
1 Labor	on / Comment Un	1			Qty	Actual	Total
1 Labor 2 Windows	on / Comment Un	1			Qty	Actual	Total
1 Labor 2 Windows	on / Comment Un	1 1	Unit Cost			Actual Unit Cost	Total
1 Labor2 Windows	on / Comment Un	1 1				Actual	Total

	place Side Door Storm D oprox. 31.5 x 79.875)	oor DR2		Componen	ts		1	nspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor			1					
2 Doors			1					
Other Detail								
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
	place Window Sill WD8. I d Air Seal Around Sill	Paint Whi	te	Componen				Inspected
and		Paint Whi	te	Componen Estimated			Actual	inspected
Comment		Paint Whi <i>Unit</i> s	te Qty	•		Qty		Inspected
Comment	d Air Seal Around Sill			Estimated	<u> </u>	Qty	Actual	
and Comment # Material / Labor 1 Labor	d Air Seal Around Sill		Qty	Estimated	<u> </u>	Qty	Actual	
and Comment # Material / Labor	d Air Seal Around Sill		Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Labor 2 Windows	d Air Seal Around Sill		Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Labor 2 Windows	d Air Seal Around Sill		Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor 1 Labor 2 Windows	d Air Seal Around Sill	Units	Qty 1 1	Estimated	<u> </u>		Actual	
# Material / Labor 1 Labor 2 Windows	d Air Seal Around Sill	Units	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor 1 Labor 2 Windows Other Detail	d Air Seal Around Sill	Units	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 5 Weatherstrip Around All Doors Comment				Componen	ts	Inspect Actual		
					Estimated			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Labor			1					
2 Doors			1					
Other Detail] [
			Measur	e Sub Total:			Sub Total:	
Manager C. Justin	tuetien Bedete			0				Inchestos
Comment -Air Sea	tration Redctn al Around Window A/C al Plumbing Opening to B	athtub in E						Inspected
Comment -Air Sea	al Around Window A/C	athtub in E		-			I Actual	Inspected
Comment -Air Sea -Air Sea	al Around Window A/C	athtub in E		ent		Qty		Inspected
Comment -Air Sea -Air Sea	al Around Window A/C al Plumbing Opening to B		Baseme	ent <i>Estimated</i>		Qty	Actual	
Comment -Air Sea -Air Sea # Material / Labor Labor	al Around Window A/C al Plumbing Opening to B		Baseme	ent <i>Estimated</i>		Qty	Actual	
Comment -Air Sea -Air Sea # Material / Labor Labor	al Around Window A/C al Plumbing Opening to B Description / Comment	Units	Baseme Qty	ent <i>Estimated</i>		Qty	Actual	
Comment - Air Sea - Air Sea # Material / Labor Labor 0 Miscellaneous Su	al Around Window A/C al Plumbing Opening to B Description / Comment	Units	Baseme Qty	ent <i>Estimated</i>		Qty	Actual	
Comment - Air Sea - Air Sea # Material / Labor Labor 0 Miscellaneous Su	al Around Window A/C al Plumbing Opening to B Description / Comment	Units	Baseme Qty	ent <i>Estimated</i>		Qty	Actual	
Comment -Air Sea -Air Sea # Material / Labor Labor 0 Miscellaneous Su	al Around Window A/C al Plumbing Opening to B Description / Comment	Units Each	Aty 1	ent <i>Estimated</i>			Actual	

Measure 7 D' Comment	WH Pipe Insulation			Componen	ts			Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
3 Other	DHW Pipe Insulation	Each	1					
Other Detail			1			1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 8 FI	oor Ins. R-19			Component		ment1		Inspected
Measure 8 FI Comment		Unite		Estimated	·		Actual	
Measure 8 FI	oor Ins. R-19 Description / Comment	Units	Qty	-		nent1		Inspected Total
Measure 8 FI Comment # Material / Labor Labor	Description / Comment Floor Insulation -	<i>Units</i> SqFt		Estimated	·		Actual	
Measure 8 FI Comment # Material / Labor	Description / Comment		Qty	Estimated	·		Actual	
Measure 8 FI Comment # Material / Labor Labor	Description / Comment Floor Insulation -		Qty	Estimated	·		Actual	
Measure 8 FI Comment # Material / Labor Labor 1 Insulation	Description / Comment Floor Insulation -		Qty	Estimated	·		Actual	
Measure 8 FI Comment # Material / Labor Labor 1 Insulation	Description / Comment Floor Insulation -		Qty 1366	Estimated Unit Cost	·	Qty	Actual Unit Cost	
Measure 8 FI Comment # Material / Labor Labor 1 Insulation	Description / Comment Floor Insulation -		Qty 1366	Estimated	·	Qty	Actual	
Measure 8 FI Comment # Material / Labor Labor 1 Insulation	Description / Comment Floor Insulation -		Qty 1366	Estimated Unit Cost	·	Qty	Actual Unit Cost	

Measure 9 Fill (Ceiling Cavity			Componen	ts A1		I	Inspected
	is an unconditioned finis e little insulation	shed attic.	Insula	te the unfinis	shed attic	areas		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Labor								
1 Insulation	Attic Insulation - Blown Cellulose - 7 in.	SqFt	904					
Other Detail						,		
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
	Monitor is Needed			Componen				Inspected
Measure 10 CO I				Estimated			Actual	
Measure 10 CO I Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty		Inspected Total
Measure 10 CO I	Description / Comment	<i>Units</i> Each		Estimated		Qty	Actual	
Measure 10 CO I Comment # Material / Labor 1 Health and Safety	Description / Comment		Qty	Estimated		Qty	Actual	
Measure 10 CO I Comment # Material / Labor 1 Health and Safety	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Measure 10 CO I Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Measure 10 CO I Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment CO monitor	Each	Qty 1	Estimated		Qty	Actual	
Measure 10 CO I Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment CO monitor	Each Hour	Qty 1 1	Estimated			Actual	

Units	Qty	Estimated				
	Qty				Actual	
	Qty	Unit Cost	Total	Qty	Unit Cost	Total
		Omi Cost	Total	Qiy		Total
Each	1					
	Measur	e Sub Total:		,	Sub Total:	
Chimney		Component	's			Inspected
		Estimated		Otv	Actual	
Chimney Units	Qty	-	ts Total	Qty		Inspected
Units		Estimated		Qty	Actual	
		Estimated		Qty	Actual	
Units	Qty	Estimated		Qty	Actual	
Units	Qty	Estimated		Qty	Actual	
Units	Qty	Estimated		Qty	Actual	
		Measur	Measure Sub Total:	Measure Sub Total:	Measure Sub Total:	Measure Sub Total: Sub Total:

-		all Kitchen Exhaust Far	n up 10'		Compone	ents			Inspected
C	omment					_			
					Estimat			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cos	t Total	Qty	Unit Cost	Total
1	Health and Safety	Kitchen exhaust fan	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
				Measur	e Sub Total	:		Sub Total:	
	Measure 14 Smo	ke Detector is Needed			Compone	ents			Inspected
					Estimat	ed		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cos	t Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail						_		
				Measur	e Sub Total	:		Sub Total:	
	Field Notes:								
			Work O	rder Gra	nd Total:		Gran	d Total:	